UI Bulletin #198c

Subject: High Voltage Disabling/Enabling

Models Years Affected: 2023-Current

Models Affected:
Chevrolet BrightDrop Electric Vans
Chevrolet Bolt EUV/EV
Chevrolet Blazer EV
Chevrolet Silverado EV

Origination Date: January 18, 2024

Revision Date: September 11, 2024

ADVISORY:

Condition/Concern:

Upfitters are often required to disable the high voltage system prior to installing any added accessories/equipment to an Electric Vehicle (EV). The procedure outlined are those that are included in the vehicle's service information.

Repair/Recommendation:

The links below are to the disabling/enabling procedures for the above listed applicable vehicles

Note: Upfitters should also review the EV Safety information in UI Bulletin 189 prior to beginning any work on an Electric Vehicle.

High Voltage Disabling - 2024 Electric vans

High Voltage Enabling - 2024 Electric vans

High Voltage Disabling - Chevrolet Bolt EUV/EV

High Voltage Enabling – Chevrolet Bolt EUV/EV

High Voltage Disabling – Chevrolet Blazer EV

High Voltage Enabling - Chevrolet Blazer EV

High Voltage Disabling – Chevrolet Silverado EV

High Voltage Enabling - Chevrolet Silverado EV

Additional Information:

Contact GM Upfitter Integration with any questions or concerns prior to or during the upfit process.

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.